

**Table 1**

**EPA, CDPH, and DTSC review of Parcel B Rad Data Evaluation**

	<b>Trench</b>	<b>Fill</b>	<b>Building Sites</b>	<b>Total</b>	<b>% of total</b>
<b>Total Survey Units in Parcel B</b>	70	110	17	197	100%
Navy recommended resampling	2	18	9	29	15%
Navy recommended reanalyzing archived samples	2	1	0	3	2%
<b>EPA, CDPH, DTSC recommend resampling</b>	55	87	7	149	76%
<b>Total recommended resampling</b>	57	105	16	178	90%
No signs of falsification found in data	13	5	1	19	10%
Regulators not yet reviewed	0	0	0	0	0%
<b>% of total recommended resampling</b>	81%	95%	94%	90%	

The above was for Parcel B alone. Below is for entire Shipyard.

<b>Total Survey Units in Hunters Pt Tetra Tech EC</b>	305	514	*
<b>Parcel B as % of total</b>	23%	21%	*

\*Parcel B has 7 former building sites, which is 21% of the total 34. The above chart shows survey units at building sites. The number of survey units at building sites for the entire site was not available.

**Table 2**

**Summary of EPA, DTSC, CDPH review of Parcel G Radiological Data Evaluation**

	<b>Trench</b>	<b>Fill</b>	<b>Building Sites</b>	<b>Total</b>	<b>% of total</b>
<b>Total Survey Units in Parcel G</b>	63	107	32	202	100%
<b>Navy recommended resampling</b>	20	53	25	98	49%
<b>EPA, CDPH, DTSC recommend resampling</b>	39	54	5	98	49%
<b>Total recommended resampling</b>	59	107	30	196	97%
<b>No signs of falsification found in data</b>	4	0	2	6	3%
<b>% of total recommended resampling</b>	94%	100%	94%	97%	

The above was for Parcel G alone. Below is for entire Shipyard.

<b>Total Survey Units in Hunters Pt Tetra Tech EC</b>	305	514	*
<b>Parcel G as % of total</b>	21%	21%	*

\* Parcel G has 4 former building sites, which is 12% of the total 34. The above chart shows survey units at building sites.

The number of survey units at building sites for the entire site was not available.